


9. EXPLODED VIEWS AND PARTS LIST

- NOTES:
- Parts marked by "NSP" are generally unavailable because they are not in our Master Spare Parts List.
 - The  mark found on some component parts indicates the importance of the safety factor of the part. Therefore, when replacing, be sure to use parts of identical designation.
 - Screws adjacent to ▼ mark on product are used for disassembly.
 - For the applying amount of lubricants or glue, follow the instructions in this manual. (In the case of no amount instructions, apply as you think it appropriate.)

9.1 PACKING SECTION



(1) PACKING SECTION PARTS LIST

Mark No.	Description	Part No.	Mark No.	Description	Part No.	
1	HEADSHEEL & CARTRIDGE ASS'Y	705-PLX500-1649	13	SPACER	507-PNTT-3467	
2	45 RPM ADAPTOR (AL)	200-DJ3000-211	14	POLYBAG FOR SLIPMAT (310 * 400 MM)	505-DJ2500H-092	A
3	POLYBAG (60 * 102 MM) (PB,CD)	505-B300-007	15	ALUMINIUM PLATTER (15 MM)	200-TT100-232C	
4	SCREW	200-ST100-268				
5	POLYBAG (PE, 35 * 50 MM)	505-S15-117	⚠	16 AC POWER CORD	See Contrast table (2)	
6	COUNTER WEIGHT ADJUSTOR ASS'Y	702-PLX500-098	17	BOX (180 * 70 * 50 MM)	507-PLX500-3600	
7	POLYFOAM	506-PLX500-700	18	PLASTIC BAG (120 * 250 MM)	505-B605-017	
8	SOFT BAG	509-PNTT-332	19	USB CABLE (L=1500 MM)	408-SUB-132	
9	I/B	See Contrast table (2)	20	SIGNAL WIRE	408-PL50-068	
10	WARRANTY CARD	See Contrast table (2)	21	POLYFOAM	506-PNTT-662A	B
11	DUST COVER & HINGE ASS'Y	See Contrast table (2)	22	GIFT BOX	See Contrast table (2)	
12	SLIPMAT	See Contrast table (2)	23	CARTON	See Contrast table (2)	
			24	POLYBAG FOR TURNTABLE	505-LP5-001	

(2) CONTRAST TABLE

PLX-500-K/LPWSYXEG, PLX-500-W/LPWSYXEG, PLX-500-K/FWUXEGCB and PLX-500-W/FWUXEGCB are constructed the same except for the following:

Mark	No.	Symbol and Description	PLX-500-K/LPWSYXEG	PLX-500-W/LPWSYXEG
	9	I/B LPWSYXEG	502-PLX500B-3626B	502-PLX500B-3626B
	9	I/B FWUXEGCB	Not used	Not used
	10	WARRANTY CARD	502-SXMK3B-3549	502-SXMK3B-3549
	11	DUST COVER & HINGE ASS'Y K	705-PLX500-1650	Not used
	11	DUST COVER & HINGE ASS'Y W	Not used	705-PLX500W-1651
	12	SLIPMAT K	612-PLX500K-095	Not used
	12	SLIPMAT W	Not used	612-PLX500W-095
⚠	16	AC POWER CORD VDE L=1900	409-DJ2-070A	409-DJ2-070A
⚠	16	AC CORD UL=1900	Not used	Not used
	22	GIFT BOX KB	507-PLX500KB-3601A	Not used
	22	GIFT BOX WB	Not used	507-PLX500WB-3601A
	22	GIFT BOX KA	Not used	Not used
	22	GIFT BOX WA	Not used	Not used
	23	CARTON KB	507-PLX500KB-3602A	Not used
	23	CARTON WB	Not used	507-PLX500WB-3602A
	23	CARTON KA	Not used	Not used
	23	CARTON WA	Not used	Not used

Mark	No.	Symbol and Description	PLX-500-K/FWUXEGCB	PLX-500-W/FWUXEGCB
	9	I/B LPWSYXEG	Not used	Not used
	9	I/B FWUXEGCB	502-PLX500A-3625A	502-PLX500A-3625A
	10	WARRANTY CARD	Not used	Not used
	11	DUST COVER & HINGE ASS'Y K	705-PLX500-1650	Not used
	11	DUST COVER & HINGE ASS'Y W	Not used	705-PLX500W-1651
	12	SLIPMAT K	612-PLX500K-095	Not used
	12	SLIPMAT W	Not used	612-PLX500W-095
⚠	16	AC POWER CORD VDE L=1900	Not used	Not used
⚠	16	AC CORD UL=1900	409-DJ2-069A	409-DJ2-069A
	22	GIFT BOX KB	Not used	Not used
	22	GIFT BOX WB	Not used	Not used
	22	GIFT BOX KA	507-PLX500KA-3601	Not used
	22	GIFT BOX WA	Not used	507-PLX500WA-3601
	23	CARTON KB	Not used	Not used
	23	CARTON WB	Not used	Not used
	23	CARTON KA	507-PLX500KA-3602	Not used
	23	CARTON WA	Not used	507-PLX500WA-3602

9.2 EXTERIOR SECTION

A

SLIPMAT
(Accessory)

ALUMINIUM PLATTER
(Accessory)

SCREW
(Accessory)

DUST COVER & HINGE ASSY (Accessory)

Grease
(GYA1004)

COUNTER WEIGHT
ADJUSTOR ASSY
(Accessory)

HEADSHEEL &
CARTRIDGE ASSY
(Accessory)

B

C

D

E

F

